SERVICE LETTER 167 REVISION A PAGE 1

SERVICE LETTER NUMBER 167 10000 PROBE JACK END PLUG LOOSENING

By: BGLASS	A: (1 MA 1 //)		Note(s):
Approved: JRS	Aircraft Makes/Model(s): AT802A AT802 (2-Place)	Float Model(s): 10000A	Mandatory Compliance Service Letter P/N 1008745
Date: 5/5/2016			
Rev: A	71002 (2-1 1400)		

FAA approval has been obtained for technical data in this publication that affects STC or TSO design compliance

EFFECTIVITY:

This service letter applies to: AT802/AT802A with Wipline 10000 Amphibious Floats installed per STC SA01795CH

COMPLIANCE:

Mandatory inspection. Inspect probe jack end plug for loosening. If loosened, mandatory compliance to service letter 167 is required. If not loose, compliance to service letter 167 is optional

BACKGROUND:

Hydraulic leak near the probe jack cylinder in the float have been reported. Upon further investigation, Wipaire have found that the end plug on the probe jack is coming loose

COMPLIANCE METHOD:

If signs of loosening are found on the end plug, safety wire probe jack cylinder front and end plugs as instructed in the work instructions of this service letter

APPROXIMATE SHOP HOURS:

Probe jack end plug removal and safety wiring will take approximately 3 hours per float

WARRANTY INFORMATION:

Parts and labor not included for this modification

TECHNICAL DATA:

Copies of this service letter, associated service kit, float service manual, and float parts manual are available at www.wipaire.com

See photos and figures below for details to aid in performing this modification

For basic float model maintenance information, see applicable Wipaire service manual at www.wipaire.com

For basic float model parts information, see applicable Wipaire parts manual at www.wipaire.com

www.wipaire.com

WORK INSTRUCTION

1. Remove (2) AN6-41A bolts and set aside for reinstallation of the probe jack cylinder




2. Gain access to the scoop tunnel assembly through the baggage compartment and by removing bulkhead 14 access panel

NOTE: If applicable, remove foam tank assembly from baggage compartment



- 3. Remove the scoop tunnel assembly top covers to gain access to the probe jack cylinder assembly
- 4. Relieve any residual pressure and disconnect the 2 hydraulic lines
- 5. Remove the probe jack cylinder assembly
- 6. If loose, tighten both plugs by securing probe jack cylinder in a stationary device and tightening both plugs firmly

7. Drill (2) 0.063" holes through probe jack end plug and probe jack front plug where shown



- 8. Attach 0.032" safety wiring through holes in a tightening direction
- 9. Reinstall probe jack cylinder assembly
- 10. Cycle scooping system checking for interference and make any adjustment as required per applicable service manual
- 11. Reassemble float as to return to service

NOTES:

- 1. Upon completion of inspection, enter information in Aircraft Logbook for completion of Wipaire Service Letter 167
- 2. Once service letter is accomplished, please visit www.wipaire.com and update your aircraft service letter/kit record using the link found on the Customer Support dropdown menu under "Update Service Letter & Kit Compliance Status"