SERVICE LETTER 158 PAGE 1 of 7 REV: B.1

SERVICE LETTER NUMBER 158							
TITLE: AIR TRACTOR SHORT FINLET INSPECTION AND SUPPORT							
BY: J. KAPSNER	AIRCRAFT MAKE/MODEL(S):	FLOAT MODEL(S):	NOTE(S):				
APP: C. WOKEN			Mandatory Compliance				
DATE: 12/30/14	AT802A	10000A	S/L P/N 1008241				
REV: B			ECO 23774				

FAA APPROVAL HAS BEEN OBTAINED FOR TECHNICAL DATA IN THIS PUBLICATION THAT AFFECTS STC OR TSO DESIGN COMPLIANCE

EFFECTIVITY:

This service letter applies to: AT802A with 10A12000-071 Short Finlets (17") installed IAW STC SA01795CH or STC SA01916CH.

COMPLIANCE:

Mandatory: Inspect Finlet attach fittings in accordance with Wipaire Service Manual

1002545, Fire Boss AT-802A Conversion on Wipline 10000 Model Floats. If

damage is found, remove and replace the Finlet.

Optional: Install optional Finlet support strut kit. One parts kit per set of (2) Finlets.

• A/C Serial No. 188 or OLDER, use KIT No. 1008241-01 (Table 1)

for outboard finlets

A/C Serial No. 189 or NEWER, use KIT No. 1008241-02 (Table 2)

for inboard finlets

BACKGROUND:

Wipaire has received a customer report that the attach fittings of a Short Finlet (P/N 10A12000-071) cracked in service. Wipaire has updated the inspection requirements for all short Finlets and has created an optional Support Strut kit designed to reduce stress on the Finlet attach fittings.

COMPLIANCE METHOD:

Conduct Visual Finlet Inspection in accordance with Wipaire Service Manual 1002545. If damage is found, remove and replace the Finlet. Install Support Strut Assy if desired.

APPROX. SHOP HOURS:

Finlet inspection will take approximately 1 hour. Support strut installation will take approximately 3 labor hours to complete per Finlet.

WARRANTY INFORMATION:

Parts and Labor not included for this modification.

TECHNICAL DATA:

Copies of this service letter, associated service kit, float service manual, and float parts manual are available on the website www.wipaire.com.

See photos below for details to aid in optional kit installation.

See Tables 1 & 2 below for a list of parts and materials applicable to this modification.

For basic Float Model maintenance information, see Wipaire applicable Service Manual on the website www.wipaire.com.

For basic Float Model parts information, see applicable Wipaire Parts Manual on the website www.wipaire.com.

SERVICE LETTER 158 PAGE 3 of 7 REV: B.1

Service Procedures: A/C Serial No. 188 or OLDER

Note: Part numbers are listed as applicable to <u>Upr-Lt or Lwr-Rt Finlet</u> / <u>Upr-Rt or Lwr-Lt Finlet</u>

- 1. Perform the following service procedures after first securing airplane.
- 2. Position Doubler 1006729 on outboard side of Finlet as shown in Figure 1. Locate and drill out (5) existing rivets.
- 3. Cleco Doubler 1006729 on Finlet and drill the remaining holes into Finlet, matching hole sizes from the doubler (3 \times Ø.193 holes, 12 \times Ø.128 holes).
- 4. Locate and cut 1 3/8" access hole. A 1 3/8" diameter Hole Saw or unibit step drill works best.
- 5. Deburr all holes.
- 6. Install Doubler 1006729 using (9) CR3213-4-2 and (3) CR3213-4-3 Cherry Max Rivets wet with sealer, using the three longer rivets in holes common to the skin splice. Also apply sealer to the backside of the Doubler before installing. Insert (3) AN3-6A Bolts in Ø.193" holes to aid in proper alignment before riveting the Doubler 1006729 in place.
- 7. Locate and drill out (2) existing rivets in horizontal tail plane near elevator as shown in Figure 2.
- 8. Open up the (2) rivet holes in Horizontal Tail Plane to Ø.193"
- 9. Deburr holes
- 10. Install the Forward Fitting 1008231/1008232 and loosely attach Strut 1008235. Insert blank end of Aft Fitting 1008233/1008234 into Strut, and attach Aft Fitting to horizontal tail (Figure 2).
- 11. Match drill two holes from the strut into the lower fitting. (Recommend marking the lower fitting, then disassembling and drilling on bench.)
- 12. Install and tighten all strut hardware as shown in Figure 3 and coat with grease.
- 13. Install Access Cover 132641-5G.
- 14. Repeat as required per Aircraft configuration.

TABLE 1 – PARTS KIT NO. 1008241- 01 (2 FINLETS)				
ITEM	QTY	PART NUMBER	DESCRIPTION	
1	2	1006729	Doubler	
2	1	1008231	Fwd Fitting, Strut, Upr Lt Finlet or Lwr Rt Finlet	
3	1	1008232	Fwd Fitting, Strut, Upr Rt Finlet or Lwr Lt Finlet (not shown)	
4	1	1008233	Aft Fitting, Strut, Upr Lt Finlet or Lwr Rt Finlet	
5	1	1008234	Aft Fitting, Strut, Upr Rt Finlet or Lwr Lt Finlet (not shown)	
6	2	1008235	Strut	
7	20	CR3213-4-2	Cherrymax Rivet (Not Shown)	
8	8	CR3213-4-3	Cherrymax Rivet (Not Shown)	
9	2	132641-5G	Cover, Access	
10	2	AN3-5A	Bolt	
11	16	AN3-6A	Bolt	
12	18	MS21044N3	Nut	
13	8	NAS1149F0332P	Washer	
14	28	NAS1149F0363P	Washer	

SERVICE LETTER 158 PAGE 4 of 7 REV: B.1

Service Procedures: A/C Serial No. 189 or NEWER

Note: Part numbers are listed as applicable to <u>Upr-Lt or Lwr-Rt Finlet</u> / <u>Upr-Rt or Lwr-Lt Finlet</u>

- 1. Perform the following service procedures after first securing airplane.
- 2. Position Doubler 1006729 on outboard side of Finlet as shown in Figure 1. Locate and drill out (5) existing rivets.
- 3. Cleco Doubler 1006729 on Finlet and drill the remaining holes into Finlet, matching hole sizes from the doubler (3 X Ø.193 holes, 12 X Ø.128 holes).
- 4. Locate and cut $1^{3}/8^{n}$ access hole. A $1^{3}/8^{n}$ diameter Hole Saw or unibit step drill works best.
- 5. Deburr all holes.
- 6. Install Doubler 1006729 using (9) CR3213-4-2 and (3) CR3213-4-3 Cherry Max Rivets wet with sealer, using the three longer rivets in holes common to the skin splice. Also apply sealer to the backside of the Doubler before installing. Insert (3) AN3-6A Bolts in Ø.193" holes to aid in proper alignment before riveting the Doubler 1006729 in place.
- 7. Locate and drill out (2) existing rivets in horizontal tail plane near elevator as shown in Figure 2.
- 8. Open up the (2) rivet holes in Horizontal Tail Plane to Ø.193"
- 9. Deburr holes
- 10. Install the Forward Fitting 1008237/1008238 and loosely attach Strut 1008236. Insert blank end of Aft Fitting 1008239/1008240 into Strut, and attach Aft Fitting to horizontal tail (Figure 2).
- 11. Match drill two holes from the strut into the lower fitting. (Recommend marking the lower fitting, then disassembling and drilling on bench.)
- 12. Install and tighten all strut hardware as shown in Figure 3 and coat with grease.
- 13. Install Access Cover 132641-5G.
- 14. Repeat as required per Aircraft configuration.

TABLE 2 - PARTS KIT NO. 1008241- 02 (2 FINLETS)				
ITEM	QTY	PART NUMBER	DESCRIPTION	
1	2	1006729	Doubler	
2	1	1008237	Fwd Fitting, Strut, Upr Lt Finlet or Lwr Rt Finlet	
3	1	1008238	Fwd Fitting, Strut, Upr Rt Finlet or Lwr Lt Finlet (not shown)	
4	1	1008239	Aft Fitting, Strut, Upr Lt Finlet or Lwr Rt Finlet	
5	1	1008240	Aft Fitting, Strut, Upr Rt Finlet or Lwr Lt Finlet (not shown)	
6	2	1008236	Strut	
7	20	CR3213-4-2	Cherrymax Rivet (Not Shown)	
8	8	CR3213-4-3	Cherrymax Rivet (Not Shown)	
9	2	132641-5G	Cover, Access	
10	2	AN3-5A	Bolt	
11	16	AN3-6A	Bolt	
12	18	MS21044N3	Nut	
13	8	NAS1149F0332P	Washer	
14	28	NAS1149F0363P	Washer	




Figure 1: Support Strut Installation (Upper Right Finlet Shown – View Looking Inboard)




Figure 2: Aft Fitting Location (Upper Right Finlet Shown - Elevator Removed)




Figure 3: Optional Support Strut Assembly - Exploded View (Upr-Lt/Lwr-Rt configuration shown)

NOTES:

- 1. Upon completion of inspection, enter information in aircraft logbook for completion of Wipaire Service Letter 158.
- 2. Once service letter is accomplished, please visit www.wipaire.com and update your aircraft service letter/kit record using the link found on the Customer Support dropdown menu under "Update Service Letter & Kit Compliance Status".
- 3. Wipaire considers the weight and balance change to be negligible for this modification.

 ### END ###