

SERVICE LETTER: #11

SUBJECT: Installation of new electric hydraulic pump motor

MODEL FLOAT: 3730 on Cessna 206 & 185
6000 on Dehaviland Beaver MK I & MK III
8000 on Cessna Caravan

SERIAL NO'S: 3730 ----S/N 37652 & down
6000 ----S/N 60078 & down
8000 ----S/N 80006 & down

COMPLIANCE REQUIRED: At owner's discretion

BACKGROUND INFORMATION:

The electric motor has been changed by the Manufacture, it is now 1 1/2" longer. The reason for the change is to prevent demagnetizing the motor's internal magnets. This change will increase the life of the motor.

METHOD OF COMPLIANCE: Install Service Kit #9

PARTS REQUIRED: See Service Kit #9

MANHOURS REQUIRED: Approx. 3 hours

Date: 6-9-87

Page: 1 of 1