

WIPAIRE, INC
INVER GROVE HEIGHTS, MINNESOTA

SERVICE LETTER: #31

DATE: January 26, 1994

SUBJECT: FIREWALL MODIFICATION

EFFECTIVITY: CESSNA CARAVAN 208 AIRCRAFT

COMPLIANCE REQUIRED: At owner's discretion.

REASON:

For aircraft operating in extreme rough water, may experience firewall buckling.

METHOD OF COMPLIANCE: Install Service Kit No. 17.

PARTS REQUIRED: Service Kit No. 17

MAN HOURS REQUIRED: 35-40 hrs

WARRANTY: None