

SERVICE LETTER: #50

DATE: NOVEMBER 06, 2000

SUBJECT: Inspection of aircraft skin rivet head interference, on float cross wire pulls.

EFFECTIVITY: All model Cessna 206 aircraft on Wipline Model 4000 and 3450 floats.

COMPLIANCE REQUIRED: None

REASON: Aircraft skin rivets may interfere with float cross wire pulls.

METHOD OF COMPLIANCE: If interference is noted, remove a small amount of dome of rivet head to clear wire pull.

PARTS REQUIRED: None

MAN-HOURS REQUIRED: N/A

WARRANTY: None