



Wipaire Worldwide
Anywhere, Anytime

SERVICE LETTER: 36

DATE: December 4, 1996

TITLE: Installation-rear strut-fitting support-13000 float.

EFFECTIVITY: DeHavilland Twin Otter, Model 300 with Wipline Model 13000 Floats Installed.

S/N 1 thru 22

REASON: When Aircraft is roughly docked nose in, floats stop abruptly and aircraft puts a forward load on the struts. This load pulls up on the rear drag strut attach bolt and may pull thru.

COMPLIANCE: If this has occurred, then compliance is immediate, if not then compliance at next 100 hr or annual inspection.

METHOD OF COMPLIANCE: Installation per Service Kit #22.

PARTS REQUIRED: KIT #22

SHOP HOURS REQUIRED: 3 Hours

WARRANTY: Parts and Labor for 18 months past the issuance of this service letter.