SERVICE LETTER: #85

DATE: June 30, 2006

EFFECTIVITY: Amphibious and Seaplane 2100, 2350, 3000, 3450, 6000, 8000 Wipline Floats

COMPLIANCE: Optional

BACKGROUND INFORMATION: Some operators have reported leaking in the baggage compartments, likely due to the age of the gaskets used to seal them from the elements.

METHOD OF COMPLIANCE: Install Service Kit #62

REPAIR HOURS REQUIRED: 4 Hours

WARRANTY: None

Rev B 1002462