

## SERVICE LETTER: 40

- DATE: November 4, 1997
- TITLE: Installation-Model 2100 Float, PA-18.

EFFECTIVITY: Piper PA-18 with 2100 Floats,

Vne Red line 129 was 138, ERROR on drawing 10D1-6008. **REASON**:

Ref: under placards. Item 6. should read,

THE AIRSPEED INDICATOR TO BE MARKED WITH A RED RADIAL LINE ON THE INDICATOR GLASS AT 129 MPH Vne.

COMPLIANCE: Within next 5 hrs, if not correct.

BACKGROUND INFORMATION: Drawing Error

METHOD OF COMPLIANCE: Revise per this Service Letter # 40.

<u>PARTS REQUIRED</u>: Wipaire decal (Red Mark)

MAN HOURS REQUIRED: N/A

WARRANTY: Parts and Labor for 18 months past the issuance of this service letter.