

 <p style="text-align: center;"> WIPAIRE, INC. <small>• MANUFACTURERS OF WIPLINE FLOATS & SKIS • SPECIALISTS IN AIRCRAFT MODIFICATION</small> <small>1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205</small> </p>			Rev <input type="text"/>
			Date 1-05-2007
Prepared by Jerry LaMere	Aircraft Make / Model Air Tractor AT-802A	Float / Ski Model 10000 Float	Page 1
FAA Reviewed <input checked="" type="checkbox"/>	Title • Installation Lower Fuselage Longeron Repair - Right Hand		
ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA			

SERVICE KIT: #68

DATE: January 05, 2007

EFFECTIVITY: Air Tractor AT-802A S/N 178 or on other S/N aircraft with similar cracks.

COMPLIANCE: As soon as possible

BACKGROUND INFORMATION: In service, the lower longeron tubes experienced cracking.

METHOD OF COMPLIANCE: Repair lower right hand longeron tubing per attached drawings, 1002199,100200, and 1002201.

PARTS REQUIRED:

DRAWINGS REQUIRED

(1) 10A02491-003 Plate	1002199
(1) 1002193 Gusset	1002200
(1) 1002189 Gusset	1002201
(1) 1002194 Sleeve	
(1) 1002191 Tube	

WARRANTY: Parts only

NOTE: All welding to be accomplished by a Air Tractor certified welder.