1700 Henry Avenue, South St. Paul, MN 55075

SERVICE LETTER: 7

SUBJECT: Main Gear Oleo Shock Strut

MODEL: 6000 & 8000 Amphibious Floats

SERIAL NO AFFECTED/EFFECTIVITY: 60001 thru 60044

COMPLIANCE REQUIRED: At Owner's Discretion

BACKGROUND INFORMATION: There has been some O-ring leaks on the main gear oleo strut. Two O-rings have been changed in the oleo assembly. One is on the cylinder piston and one is on the cylinder retainer. The felt wiper in the retainer has been changed to a nitrile rubber wiper. The O-ring and wiper grooves have to be cut larger to make this change.

METHOD OF COMPLIANCE: Install per Service Kit No 6.

PARTS REQUIRED: Items 5, 6 and 7 (O-rings and wipers) from Kit No 6 and revised piston and cylinder retainer.

HOURS REQUIRED: Approximately three shop hours.

DATE: 12-26-1984

Rev A 1002386