



Wipaire Worldwide
Anywhere, Anytime

SERVICE LETTER: 42

DATE: April 26, 1999

SUBJECT: FIREWALL MODIFICATION

EFFECTIVITY: Cessna 208 Caravan with 8000 floats

COMPLIANCE REQUIRED: At owner's discretion.

REASON:

For aircraft operating in extreme rough water, may experience firewall buckling.

METHOD OF COMPLIANCE: Install Service Kit No. 24.

PARTS REQUIRED: Service Kit No. 24

SHOP HOURS REQUIRED: 35-50 hrs

WARRANTY: Not applicable