SERVICE LETTER: #63

DATE: April 6, 2004

SUBJECT: Addition of vent ball stop

EFFECTIVITY: AT-802A Fire Boss S/N 154,155,168,169

COMPLIANCE REQUIRED: NONE

REASON: To keep landplane vent check ball open for scooping operations.

METHOD OF COMPLIANCE: Before scooping operations, install stop per

Service Kit #44

PARTS REQUIRED: Noted on Service Kit #44

SHOP HOURS REQUIRED: 1 Hr.

WARRANTY: Parts only for 18 months past the original issuance date of this

service letter.

NOTE: Remove for landplane operations.

Rev A 1002441