

 <p style="text-align: center;"> <b>• MANUFACTURERS OF WIPLINE FLOATS &amp; SKIS</b>  <b>• SPECIALISTS IN AIRCRAFT MODIFICATION</b> </p> <p style="text-align: center;"> <small>1700 Henry Avenue - Fleming Field  South St. Paul, MN 55075  651-451-1205</small> </p>			Rev B
			Date 4/20/06 Revised 1/10/10
Prepared by Ellen Parker	Aircraft Make / Model AT-802	Float / Ski Model Wipline 10000 Amphibious Floats	Page 1 2
FAA Reviewed <input checked="" type="checkbox"/>	Title AT-802 Adding Larger Water Rudder Stop on Aft Bulkhead		
<b>ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA</b>			

**SERVICE LETTER: #81**

**DATE: 4/20/06**

**EFFECTIVITY: AT-802 S/N 10001-10052A with 10000 Amphib. Floats Installed. Later S/N's will have the larger pad (plate) added during production at Wipaire, Inc.**

**COMPLIANCE: Compliance is required but at the operator's earliest convenience.**

**BACKGROUND INFORMATION: On some of the aircraft, the water rudder blade stops are rubbing above the stop-pad (plate).**

**METHOD OF COMPLIANCE: A larger pad (plate) is required using this Service Letter in conjunction with the associated Service Kit #58 and the installation instructions found there.**

**REPAIR HOURS REQUIRED: 1 hour**

**WARRANTY: Parts Only for 18 months past the original issuance date of this service letter.**

