## **SERVICE LETTER:** #82

**DATE: May 31, 2006** 

**EFFECTIVITY:** AT-802 aircraft with Wipline 10000 Amphibious Floats

**COMPLIANCE:** Required if flat upper forward strut is distorted, or at next scheduled 100 Hr. Inspection.

**BACKGROUND INFORMATION:** Unsymmetrical loads when taking off or landing will cause the upper forward flat strut to distort.

**METHOD OF COMPLIANCE:** Install Service Kit #59.

**PARTS REQUIRED:** Parts listed in Service Kit #59.

**REPAIR HOURS REQUIRED: 2 Hours** 

WARRANTY: Parts only for 18 months past the original issuance date of this service letter.

Rev B 1002460