



SERVICE LETTER NUMBER 111			
TITLE: 8000 FLOAT WATER RUDDER LOCK ENHANCEMENT			
BY: J. SORTOR	AIRCRAFT MAKE/MODEL(S):	FLOAT MODEL(S):	NOTE(S):
APP: D. GARRETT	CESSNA 208 CARAVAN	8000 AMPHIBIOUS OR SEAPLANE	OPTIONAL COMPLAINECE
DATE: 25-JAN-2012			S/L P/N 1005028
REV: B			ECO--22156

FAA APPROVAL HAS BEEN OBTAINED FOR TECHNICAL DATA IN THIS PUBLICATION THAT AFFECTS STC OR TSO DESIGN COMPLIANCE

EFFECTIVITY:

This Service Letter applies to all Wipline model 8000 amphibian floats, as installed on Cessna 208 Caravan aircraft. This Service Letter applies to Cessna 208 Caravan aircraft equipped with STC SA1311GL.

COMPLIANCE:

Service Letter compliance is optional and recommended.

BACKGROUND:

This enhancement is provided as per customer request.

COMPLIANCE METHOD:

Remove and replace parts and hardware identified in Service Kit 79 Figure 1 and Figure 2.

APPROX. SHOP HOURS:

This Service Letter will take an estimated 4 hours to complete.

WARRANTY INFORMATION:

Parts and labor warranty is not included for this modification.

TECHNICAL DATA: See Service Kit 79, P/N 1005029

NOTES:

NONE

END