

WIPAIRE, INC.
INVER GROVE HEIGHTS, MINNESOTA

SERVICE LETTER: #12

SUBJECT: Water rudder,rivet shear between main blade and doubler supports.

FLOAT MODEL: 8000 Amphibious

SERIAL NO.: 80001 THRU 80008

COMPLIANCE REQUIRED: At owner's discretion

BACKGROUND INFORMATION: There have been reports of rivet shear between the main blade and the 1/8" doubler supports. It is recommended that more rivets be added see sketch.

METHOD OF COMPLIANCE: Add rivets per sketch

PARTS REQUIRED: Rivets noted

MAN HOURS REQUIRED: 1 Hour

Date: 6-23-87

Page: 1 of 1