

 <p style="text-align: center;"> WIPAIRE, INC. <small>* MANUFACTURERS OF WIPLINE FLOATS & SKIS * SPECIALISTS IN AIRCRAFT MODIFICATION</small> <small>1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205</small> </p>			Rev 1
			Date 8/30/06
Prepared by Ellen Parker	Aircraft Make / Model DeHavilland MK I & MK III	Float / Ski Model	Page 1 1
FAA Reviewed <input checked="" type="checkbox"/>	Title Installation of "Seat Locked" warning placard.		
ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA			

SERVICE LETTER: # 17

DATE: Revision A, 8/30/06

EFFECTIVITY: This is mandatory for MK I & III Beavers with pilot, co-pilot, and rear seats installed per Wipaire, Inc. STC SA711GL.

COMPLIANCE: Mandatory, shall be accomplished within the next 10 hours of operation.

BACKGROUND INFORMATION: This is a precautionary placard to remind pilots to be sure the seats are locked securely.

METHOD OF COMPLIANCE: Install placard in full view of the pilot!
This placard is adhesive backed, so for installation, just make sure panel surface is clean and dry before application.

PARTS REQUIRED: P/N 0705097-1 (Wipaire 5A3-716)

REPAIR HOURS REQUIRED: Less than 1 Hour.

WARRANTY: None