

WIPAIRE, INC.
INVER GROVE HEIGHTS, MINNESOTA

SERVICE LETTER: #40

DATE: November 4, 1997

TITLE: Installation-Model 2100 Float, PA-18.

EFFECTIVITY: Piper PA-18 with 2100 Floats,

REASON: Vne Red line 129 was 138, ERROR on drawing 10D1-6008.

Ref: under placards. Item 6. should read,

THE AIRSPEED INDICATOR TO BE MARKED WITH A RED RADIAL
LINE ON THE INDICATOR GLASS AT 129 MPH Vne.

COMPLIANCE: Within next 5 hrs, if not correct.

BACKGROUND INFORMATION: Drawing Error

METHOD OF COMPLIANCE: Revise per this Service Letter # 40.

PARTS REQUIRED: Wipaire decal (Red Mark)

MAN HOURS REQUIRED: N/A

WARRANTY: Parts only.

COMPLIANCE SIGNATURE AND RETURN TO WIPAIRE, INC.

YES _____ NO _____

SIGNATURE: _____ DATE: _____