1700 Henry Avenue, South St. Paul, MN 55075

SERVICE LETTER NO: 25

DATE: 05-01-1992

SUBJECT: Reinforcement of Model 4000 Float Hull Bulkheads

MODEL: 4000 Floats

SERIAL NO AFFECTED/EFFECTIVITY: Cessna Aircraft Model 206 or 185 with Wipline Model 4000 Amphibian/Seaplane Floats. Applicable S/N's: 1-16, 19-22, 25-54, 57-60, 74 and 75.

COMPLIANCE REQUIRED: At Owner's Discretion or if inspection of these float bulkheads show signs of buckling.

BACKGROUND INFORMATION: Some aircraft operated in extremely rough water may experience buckling on float bulkheads, next to the keel. Reference Bulkheads 3,4,5,6,7.

METHOD OF COMPLIANCE: Installation of reinforcing angles and doublers per Service Kit No 10.

WARRANTY: Parts and labor for 18 months after the issuance date of this service letter.

WEIGHT AND BALANCE CHANGE: WEIGHT ARM MODEL

6 LBS +5.0 206 6 LBS 0.0 185

Rev A 1002403