



Wipaire Worldwide  
Anywhere, Anytime

## **SERVICE LETTER: #57**

DATE: September 9, 2002

REISSUED: October 1, 2003

TITLE: Axle-Nose Gear Trolley-Replacement

EFFECTIVITY: 2100A S/N's: 21412A & DN  
2350A S/N's: 23052A & DN  
3000A S/N's: 30048A & DN  
3450A S/N's: 34034A & DN

COMPLIANCE: At the next 100 hr or annual inspection, Inspect nose gear trolley axle, if they are tube type, check for deformation in the area of the slide bearings also bearings may be damaged also. If the axles are out round, replace with P/N 34A07509-008 axle.

### **BACKGROUND INFORMATION:**

There is the possibility of your trolley axles becoming out of round, thru hard landings, rough taxi ways, and or rough landing strips.

METHOD OF COMPLIANCE: Replace tube type axles with solid axles, P/N 34A07509-008 (2 per trolley), slide bearings may need to be replaced also if axle holes are out of round.

SHOP HOURS REQUIRED: 2 Hrs.

WARRANTY: Parts only for 18 months past the original issuance of this service letter.