



Wipaire Worldwide
Anywhere, Anytime

SERVICE LETTER #27

DATE: July 21, 1992

TITLE: Reinforcement of Glareshield and "V" Brace

EFFECTIVITY: Cessna Aircraft, Model 206 with Wipline Model 4000 Floats Installed.

REASON: Aircraft operated in rough water may experience oil canning or buckling of the aircraft glareshield.

COMPLIANCE: At owner's discretion.

METHOD OF COMPLIANCE: Install doublers and reinforcement strips per Service Kit #11.

WARRANTY: Parts and Labor for 18 months past the issuance of this service letter.