



Wipaire Worldwide
Anywhere, Anytime

SERVICE LETTER: #41

DATE: July 27, 1998

TITLE: Installation - nose wheel plunger

EFFECTIVITY: 2100 Floats S/N's:

21001, 21002, 21007, 21008, 21011 thru 21014, 21017 thru 21020, 21025,
21026, 21031, 21032, 21035 thru 21052, 21055 thru 21068, 21071 thru 21074
21083 thru 21088

2350 Floats S/N's:

23003, 23004, 23009 thru 23012, 23015 thru 23020

REASON: Nose wheel plunger material change, old material was effected by
moisture swelling

COMPLIANCE: Within next 5-10 hrs,

BACKGROUND INFORMATION: Nose wheel shimmy, caused by position lock inoperative.

METHOD OF COMPLIANCE: Install Service Kit #23

PARTS REQUIRED: Kit #23

SHOP HOURS REQUIRED: 2 hrs

WARRANTY: Parts and Labor for 18 months past the issuance of this service letter.