



Wipaire Worldwide  
Anywhere, Anytime

**SERVICE LETTER:** 50

**DATE:** NOVEMBER 06, 2000

**SUBJECT:** Inspection of aircraft skin rivet head interference, on float cross wire pulls.

**EFFECTIVITY:** All model Cessna 206 aircraft on Wipline Model 4000 and 3450 floats.

**COMPLIANCE REQUIRED:** None

**REASON:** Aircraft skin rivets may interfere with float cross wire pulls.

**METHOD OF COMPLIANCE:** If interference is noted, remove a small amount of dome of rivet head to clear wire pull.

**PARTS REQUIRED:** None

**SHOP-HOURS REQUIRED:** N/A

**WARRANTY:** None