

SERVICE LETTER: #66

DATE: August 9, 2004

SUBJECT: Nose wheel shimmy

EFFECTIVITY: Wipline Amphibious Model 2100 S/N 21001 thru 21538 2350 S/N 23001 thru 23072 3000 S/N 30001 thru 30136 3450 S/N 34001 thru 34160

COMPLIANCE REQUIRED: No

REASON: Operators noticing nose wheel shimmy

METHOD OF COMPLIANCE: At owner's discretion, install Service Kit #48

PARTS REQUIRED: Service Kit #48

SHOP HOURS REQUIRED: 1.5 hours

WARRANTY:

- A. Parts only (\$250.00 core charge) for 18 months past the original issuance date of this service letter.
- B. \$250.00 will be credited with return of the old blocks.
- C. Exchange old pivot blocks for the set that is modified in Service Kit #48