

 <p style="text-align: center;"> WIPAIRE, INC. <small>1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205</small> </p> <p style="text-align: center; color: red;"> • MANUFACTURERS OF WIPLINE FLOATS & SKIS • SPECIALISTS IN AIRCRAFT MODIFICATION </p>			Rev/ 1 st Release C / 5-2-07
			Date 8-3-10
Prepared by Ellen Parker	Aircraft Make / Model AT-802 Fire Boss Conversion	Float / Ski Model 10000 Series Fire Boss Floats	Page 1 1
FAA Reviewed <input checked="" type="checkbox"/>	Title Fire Boss Foam Tank Securing		
ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA			

SERVICE LETTER: 94

EFFECTIVITY: AT-802 Fire Boss Float s/n 10109-10110 and below.

COMPLIANCE: At owner/operators discretion install Service Kit 72

BACKGROUND INFORMATION:

In the initial release, this was mainly a problem of the cannon plug P/N 206429-1 breaking from being bumped when the plastic foam tank inside the floats moved during flight. Later reports indicated damage to the surrounding bulkhead. In a continuing effort to solve this problem, we have made several more modifications to the area to help secure the tank and the area surrounding it.

METHOD OF COMPLIANCE: A new foam tank and associated hardware is included with Service Kit 72 and are recommended upgrades for the security of the foam tank and the surrounding area.

SHOP HOURS REQUIRED: 1-3 hours per float

WARRANTY: 10% parts discount for 18 months subsequent to Service Kit # 72 release date of 3/30/10.