



Wipaire Worldwide
Anywhere, Anytime

1700 Henry Avenue, South St. Paul, MN 55075

SERVICE LETTER NO: 1

SUBJECT: Hydraulic Motor Circuit Breaker

MODEL: W6000 Amphibious Floats

SERIAL NO AFFECTED/EFFECTIVITY: 60001 thru 60006, 60011 thru 60012

COMPLIANCE REQUIRED: At owner's discretion

BACKGROUND INFORMATION: The two hydraulic pumps are powered through a single circuit breaker. If this circuit breaker opens due to the malfunction of either motor, both motors will be inoperative. The incorporation of dual circuit breakers at the motors will allow continued operation on one motor after the circuit breaker for one motor has opened. These circuit breakers are to be located in the left float, and cannot be reset in flight. The main circuit breaker remains in the cockpit and may be reset in flight.

METHOD OF COMPLIANCE: Install Service Kit No 1.

PARTS REQUIRED: As provided in Service Kit No 1.

MANHOURS REQUIRED: Approximately two man hours.

DATE: 04-26-1983