



Wipaire Worldwide  
Anywhere, Anytime

**SERVICE LETTER: #44**

DATE: March 24, 2000

SUBJECT: Firewall Modification

EFFECTIVITY: Cessna 208 Caravan: this firewall reinforcement required on aircraft that don't have approved firewall reinforcement already installed from the factory. This modification required with Wipaire Inc. 8000 Float installation.

COMPLIANCE REQUIRED: This is an Optional Modification, and is at owner's discretion.

REASON:

For aircraft operating in extremely rough water, may experience firewall buckling.

METHOD OF COMPLIANCE: Install Service Kit No. 25.

PARTS REQUIRED: Service Kit No. 25

SHOP HOURS REQUIRED: 300 hrs

WARRANTY: NONE