



Wipaire Worldwide
Anywhere, Anytime

SERVICE LETTER: #53

DATE: June 3, 2002

TITLE: Installation – Chinese Baggage Placards.

EFFECTIVITY: Required on Cessna 208 Caravan aircraft with Wipline Model 8000 floats, Registered in China. S/N's: 80211A, 80212A, 80213A, 80214A, 80227A, 80228A, 80247A, 80248A .

COMPLIANCE: Immediate.

BACKGROUND INFORMATION: Cessna 208 Caravan Aircraft with Wipline 8000 Floats, are required to have float baggage compartment placards in Chinese.

METHOD OF COMPLIANCE: Install 6B3-2250-3 placard in the forward baggage compartment & 6B3-2250-4 placard in the aft baggage compartment. Locate baggage compartment placards adjacent to existing baggage placards on the inside of the baggage doors.

PARTS REQUIRED: Placards P/N's 6B3-2250-3 (2) & 6B3-2250-4 (2).

MAN HOURS REQUIRED: 1/2 Hr.

WARRANTY: Parts and labor for 18 months past the original issuance date of this service letter.