

**SERVICE LETTER: #60**

DATE: June 16, 2003

TITLE: Installation of Pressure Switch Diode.


EFFECTIVITY-FLOAT S/N's: 3730 Amphibious Float Installation

COMPLIANCE: Revise your parts and service manuals.

**BACKGROUND INFORMATION:**

There is an illustration error in the electrical schematics, for the Installation of the diode, for the hydraulic pressure switch.

METHOD OF COMPLIANCE: Ref: electrical schematics in your parts and service manuals, correct the diode installation as shown.



MAN HOURS REQUIRED: N/A

WARRANTY: N/A