

 <p style="text-align: center;"> • MANUFACTURERS OF WIPLINE FLOATS & SKIS • SPECIALISTS IN AIRCRAFT MODIFICATION </p> <p style="text-align: center; font-size: small;"> 1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205 </p>			Rev B
			Date 04/06/06 Revised 1/10/10
Prepared by Ellen Parker	Aircraft Make / Model AT-802 S/N 10001-10052	Float / Ski Model 10000 Amphibious Floats	Page 1 / 1
FAA Reviewed <input checked="" type="checkbox"/>	Title AT-802 Fire Boss brake line lengthening		
ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA			

SERVICE LETTER: #78

DATE: 04/06/2006

TITLE: AT-802 Fire Boss Brake Lines

EFFECTIVITY: All AT-802 aircraft with Wipline 10000 Amphibious Floats serial number 10001 through 10052

COMPLIANCE: Not Mandatory

BACKGROUND INFORMATION: Through customer reports, it has been determined that the brake calipers would be easier to remove if the hoses were lengthened. By lengthening the hose running from the bulkhead to the brake caliper, enough slack is created to remove the calipers easily for maintenance. All Wipaire production or replacement hoses on this model of floats in this location will be 2" longer.

METHOD OF COMPLIANCE: Install Service Kit #57.

HOURS REQUIRED: 2

WARRANTY: none