

1700 Henry Avenue, South St. Paul, MN 55075

SERVICE LETTER: 8

SUBJECT: Link-Nose Gear Truck to Ram

MODEL: 6000 Amphibious Floats

SERIAL NO AFFECTED/EFFECTIVITY: 60001 thru 60054

COMPLIANCE REQUIRED: Inspect immediately and each 100 hrs until replacement with improved part.

BACKGROUND INFORMATION: There have been four reports of failure or cracks around the link connecting the Nose-Gear Truck to the Ram. This Nose-Gear Link is located on the forward end of ram and attaches to gear truck of nose gear. The most likely cause of this failure is a severe shimmying or repeated severe side-loads.

INSPECTION: Inspect the link and the area about it for cracks and comply as directed.

METHOD OF COMPLIANCE: If cracked, replace with part number 6A07204-001 or most recent revision.

DATE: November 25, 1985

WARRANTY: None Offered