| | | NUFACTURERS OF WIPLINE FLOATS & SKIS PECIALISTS IN AIRCRAFT MODIFICATION 1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205 | Rev A Date 1/27/2006 | |
|---|---|---|-------------------------------|--|
| Prepared by Ellen Parker | Aircraft Make / Model HUSKY A-1B with 110" Flaps Installed | Float / Ski Model MODEL 2100 FLOATS | Page 1 2 | |
| FAA Reviewed | Title UPDATES FOR THE HUSKY LONG FLAP INSTA | LLATION | V | |
| ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA | | | | |

SERVICE KIT: # 56

DATE: September 30, 2007

EFFECTIVITY: Aircraft Serial #2285, 2288, 2289, 2291 & Up

COMPLIANCE: Install P/N 21A08154-009 Rudder Stops as per Wipaire Installation Drawing 10C1-6019. After this is accomplished, the hardware and other included parts need to be added to the required inspections at 100 Hour or Annual Inspection and inspected accordingly.

BACKGROUND INFORMATION: Flight testing has shown that the Husky A-1B's with the 110" flaps require water rudder stops to be installed to meet the minimum flight stability requirements.

METHOD OF COMPLIANCE: Install the rudder stops as per Wipaire Installation Drawing 10C1-6019.

PARTS REQUIRED:

KIT P/N 1002537 which includes the following:

| 21A08154-009 Stop | (4) |
|-------------------------|------------|
| 21A08156-130 Plate Stop | (4) |
| AN4-7A Bolt | (2) |
| AN3-7A Bolt | (2) |
| NAS1149D0416J Washer | (4) |
| NAS1149F0363P Washer | (4) |
| MS21083N4 Nut | (4) |
| MS21044N3 Nut | (4) |
| 10C1-6019 Drawing | |

WARRANTY: Parts - All Aircraft; Labor - Aircraft Under Warranty

